


Measuring Connector Length

01. Start the measuring tape on the inside of the cuff, just under the band.

02. Hold connector so that it is straight and in-shape. There is no need to pull or tighten the connector. Hold the tape measure across the length to measure.

03. Finish the measuring tape on the inside of the cuff, just under the band. In this case, the connector is 1,200mm



TOLERANCES

All connectors are cut and welded individually to ensure quality. There can be a slight variation on length within the tolerances listed below.

Length: 80mm - 250mm tolerance: -0mm to +5mm

Length: 300mm - 800mm tolerance: -0mm to +10mm

Length: 800mm+ tolerance: -0mm to +20mm